

ACURA B2248: HIP POWER SUPPLY ABNORMAL (MORE THAN 16 V)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes

What Does The Acura B2248 Code Mean?

The HIP Power Supply is abnormally high.

What Are The Potential Causes Of The Acura B2248 Code?

- Faulty charging system
- AcuraLink control unit needs to be updated with the latest software
- Faulty AcuraLink control unit

Reference Sources

[Acura B2248](#), DTCDECODE.