

ACURA B2249: HIP POWER SUPPLY ABNORMAL (LESS THAN 9 V)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2249 Code Mean?

This code indicates that the HIP Power Supply is abnormally low.

What Are The Potential Causes Of The Acura B2249 Code?

Below are some potential causes of this DTC:

- Faulty battery or +B line
- Faulty AcuraLink control unit

Reference Sources

[Acura B2249](#), DTCDECODE.