

ACURA B2965: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH REAR CLIMATE CONTROL PANEL

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B2965 Code Mean?

Poor communication between the Climate Control Unit and the Rear Climate Control Panel.
(Climate Control malfunction)

What Are The Potential Causes Of The Acura B2965 Code?

- Loose wires or poor connections on the rear climate control panel and climate control unit circuit
- "Open" in the wire between the No. 30 (10 A) fuse in the under-dash fuse/relay box and the rear climate control panel
- "Open" in the wire between the rear climate control panel and body ground Poor ground at G506
- "Open" in the wire(s) between the climate control unit and the rear climate control panel
- Faulty Rear Climate Control Panel

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2965](#) - Pages 99-102.