

ACURA B2975: OPEN IN THE DRIVER'S VENT AIR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2975 Code Mean?

This code indicates that the Driver's Vent Air sensor circuit is "Open".

What Are The Potential Causes Of The Acura B2975 Code?

Below are some potential causes of this DTC:

- Perform the self-diagnostic with the HDS or the climate control unit
- Loose wires or poor connections on the driver's vent air temperature sensor circuit
- "Open" circuit between the climate control unit and the driver's vent air temperature sensor
- Faulty driver's vent air temperature sensor
- Faulty climate control unit

Reference Sources

[Acura B2975](#), DTCDECODE.