

ACURA B2979: OPEN IN THE A/C PRESSURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$280
Can I Still Drive?	:	Yes

What Does The Acura B2979 Code Mean?

Open in the A/C Pressure Sensor Circuit. A/C compressor inoperative.

What Are The Potential Causes Of The Acura B2979 Code?

- Loose wires or poor connections on the A/C pressure sensor circuit
- "Open" in the wire(s) between the climate control unit and the A/C pressure sensor
- Faulty A/C Pressure Sensor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2979](#) - Pages 110-112.