

ACURA B2984: PROBLEM IN THE DRIVER'S COOL VENT CONTROL LINKAGE, DOOR, OR MOTOR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2984 Code Mean?

This code indicates that the Driver's Cool Vent Control malfunction is detected.

What Are The Potential Causes Of The Acura B2984 Code?

Below are some potential causes of this DTC:

- Perform the climate control self-diagnostic with the HDS or the climate control unit
- Loose wires or poor connections on the driver's cool vent control motor circuit
- Faulty driver's cool vent control motor
- Faulty climate control unit

Reference Sources

[Acura B2984](#), DTCDECODE.