

ACURA B2985: PROBLEM IN THE PASSENGER'S COOL VENT CONTROL LINKAGE, DOOR, OR MOTOR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes

What Does The Acura B2985 Code Mean?

Passenger's Cool Vent Control malfunction detected.

What Are The Potential Causes Of The Acura B2985 Code?

- Perform the climate control self-diagnostic with the HDS or the climate control unit
- Loose wires or poor connections on the passenger's cool vent motor circuit
- Faulty passenger's cool vent control motor, vent control linkage or door
- Faulty climate control unit

Reference Sources

[Acura B2985](#), DTCDECODE.