

ACURA B2987: PROBLEM IN THE REAR VENT CONTROL LINKAGE, DOOR, OR MOTOR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes

What Does The Acura B2987 Code Mean?

Rear Vent Control malfunction detected.

What Are The Potential Causes Of The Acura B2987 Code?

- Perform the climate control self-diagnostic with the HDS or the climate control unit
- Loose wires or poor connections on the rear vent control motor circuit
- Faulty rear vent control motor, vent control linkage or door
- Faulty climate control unit

Reference Sources

[Acura B2987](#), DTCDECODE.