

ACURA B2991: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH AUDIO UNIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2991 Code Mean?

This code indicates poor communication between the Climate Control Unit and the Audio Unit.

NOTE: Do the self-diagnostic function with the HDS.

What Are The Potential Causes Of The Acura B2991 Code?

Below are some potential causes of this DTC:

- Loose wires or poor connections on the rear climate control panel and climate control unit circuit
- "Open" or "Short in the wire(s) between the climate control unit and the audio unit.
- Faulty Audio Unit
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2991](#) - Pages 121-122.