

ACURA P1162: AIR FUEL SENSOR (BANK 1 SENSOR 1) CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Acura P1162 Code Mean?

DTC [P0131](#), [P0132](#), [P0133](#), [P1163](#) not set, vehicle driven while in closed loop at over 55 mph in D4 for 1-2 minutes, and the PCM detected an unexpected voltage condition on the A/F circuit during the HO2S Monitor test.

What Are The Potential Causes Of The Acura P1162 Code?

- A/F sensor may be contaminated or may have failed
- Fuel supply system is too lean (exhaust leaks in front of HO2S)
- Fuel supply system is too rich (fuel filter is clogged or dirty)
- PCM has failed

Reference Sources

[Acura P1162](#), DTCDECODE.