

What Does The Acura P1167 Code Mean?

Engine runtime over 80 seconds, and the PCM detected an unexpected voltage condition on the A/F sensor Heater circuit.

What Are The Potential Causes Of The Acura P1167 Code?

- A/F sensor heater power supply circuit is open (check the fuse)
- A/F sensor heater circuit is shorted to system power (B+)
- A/F sensor heater is damaged or has failed
- PCM has failed

Reference Sources

Acura P1167, DTCDECODE.

