

ACURA P1201: CYLINDER 1 MISFIRE DETECTED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Does The Acura P1201 Code Mean?

Condition for setting the DTC: Engine runtime 10 seconds, engine under positive load conditions, and the PCM detected a random misfire condition in one cylinder during the 200 (Catalyst) or 1000 revolution (Emission) test range.

What Are The Potential Causes Of The Acura P1201 Code?

Below are some potential causes of this DTC:

- Air leaks (intake) or exhaust leaks affecting only one cylinder
- Base engine (compression) problem affecting only one cylinder
- Fuel metering (fuel injector dirty) problem affecting one cylinder
- Ignition system (spark plug or wire) fault affecting

Reference Sources

[Acura P1201](#), DTCDECODE.