

ACURA P1244: INSUFFICIENT CLOSED THROTTLE POSITION DETECTED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura P1244 Code Mean?

Condition for setting the DTC:

Engine running at road load, with at least one wide-open throttle event, and the PCM detected insufficient closed throttle position.

What Are The Potential Causes Of The Acura P1244 Code?

Below are some potential causes of this DTC:

- Throttle valve is stuck, damaged or has failed
- TP sensor is damaged or has failed

Reference Sources

[Acura P1244](#), DTCDECODE.