

## ACURA P1318: SPARK PLUG DETECTION MODULE RESET CIRCUIT FAULT (BANK 2)

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$500
Can I Still Drive?	:	No

### What Does The Acura P1318 Code Mean?

Engine started, and the PCM detected an unexpected condition on the Spark Plug Detection Module Reset circuit for Cylinder Bank 2.

### What Are The Potential Causes Of The Acura P1318 Code?

- Spark Plug Detection Module circuit open or shorted to ground
- Spark Plug Detection Module circuit is shorted to system power
- Spark Plug Detection Module is damaged or has failed
- PCM has failed

### Reference Sources

[Acura P1318](#), DTCDECODE.