

ACURA P1336: CRANKSHAFT POSITION SENSOR 'B' CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes

What Does The Acura P1336 Code Mean?

Engine started, and PCM detected an interruption of the CKP Sensor 'B' signal during the CCM test.

What Are The Potential Causes Of The Acura P1336 Code?

- CSF 'B' signal circuit is open or shorted to ground
- CSF 'B' signal circuit is shorted to VREF or system power (B+)
- CSF 'B' is damaged or has failed
- CSF 'B' pickup assembly or its pulse rotor is damaged
- PCM has failed

Reference Sources

[Acura P1336](#), DTCDECODE.