

ACURA P1337: CRANKSHAFT POSITION SENSOR 'B' CIRCUIT NO SIGNAL

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes

What Does The Acura P1337 Code Mean?

Engine cranking or running; and the PCM did not detect any signals from the Crankshaft Position (CKP) 'B' sensor during the CCM test.

What Are The Potential Causes Of The Acura P1337 Code?

- CKP Sensor 'B' signal circuit is open or shorted to ground
- CKP Sensor 'B' signal circuit is shorted to VREF or power
- CKP Sensor 'B' is damaged or has failed
- CKP Sensor 'B' pickup assembly or its pulse rotor is damaged
- PCM has failed

Reference Sources

[Acura P1337](#), DTCDECODE.