ACURA P1459: EVAP PURGE FLOW SWITCH CIRCUIT MALFUNCTION		
OVERVIEW		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$200
Can I Still Drive?	:	Yes

What Does The Acura P1459 Code Mean?

Engine running at cruise speed and than back to idle speed, ECT sensor signal more than 154°F, and the PCM detected an unexpected voltage condition on Purge Flow switch circuit.

What Are The Potential Causes Of The Acura P1459 Code?

- Purge flow switch is open, shorted to ground or to power (B+)
- Purge flow switch vacuum line is loose, bent or damaged
- Purge flow switch is damaged or has failed
- PCM has failed

Reference Sources

Acura P1459, DTCDECODE.

