

ACURA P1508: IDLE AIR CONTROL VALVE CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$120-\$500
Can I Still Drive?	:	Yes

What Does The Acura P1508 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the IAC valve control circuit during the test.

What Are The Potential Causes Of The Acura P1508 Code?

- IAC valve control circuit is open or shorted to ground
- IAC valve control circuit is shorted to system power (B+)
- IAC valve power circuit is open or shorted to ground
- IAC valve is damaged or has failed
- PCM has failed
- TSB 03-006 (3/17/03)

Reference Sources

[Acura P1508](#), DTCDECODE.