

ACURA P1739: A/T 3RD PRESSURE SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Acura P1739 Code Mean?

Engine running in gear, and the PCM detected an unexpected voltage condition on the 3rd pressure switch circuit during the test.

What Are The Potential Causes Of The Acura P1739 Code?

- A/T 3rd pressure switch signal circuit is open
- A/T 3rd pressure switch signal circuit is shorted to ground
- A/T 3rd pressure switch signal circuit shorted to system power
- A/T 3rd pressure switch is damaged or has failed
- TCM or PCM has failed

Reference Sources

[Acura P1739](#), DTCDECODE.