

ACURA P1745: PROBLEM IN SHIFT CONTROL SYSTEM; SERVO CONTROL VALVE STUCK OFF OR SERVO VALVE STUCK OFF

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Does The Acura P1745 Code Mean?

Condition for setting the DTC:

The engine speed flares when upshifting to 2nd-3rd, the engine speed flares when upshifting to 3rd-4th, driving in 5th gear neutral condition. The execution time is continuous and the duration time is 1-2 seconds or more.

NOTE: Before you troubleshoot, record all freeze data and any on-board snapshot.

What Are The Potential Causes Of The Acura P1745 Code?

Below are some potential causes of this DTC:

- Low or dirty transmission fluid
- If the strainer has metal debris or excessive clutch material, replace the transmission
- Faulty servo control valve in the main valve body, servo valve in the regulator valve body, or replace the main valve body, regulator valve body
- Faulty transmission

Reference Sources

[Acura P1745](#), DTCDECODE.