

ACURA P1751: A/T HYDRAULIC PRESSURE CONTROL MALFUNCTION (MECHANICAL)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$500
Can I Still Drive?	:	Yes

What Does The Acura P1751 Code Mean?

Engine started, engine running in gear, and the PCM detected a mechanical fault existed in the hydraulic portion of the A/T (as it relates to Clutch Pressure Control Solenoids 'A' and 'B') during the CCM test.

What Are The Potential Causes Of The Acura P1751 Code?

- Clutch Pressure Control Solenoid 'A' is damaged or has failed
- Clutch Pressure Control Solenoid 'B' is damaged or has failed
- Shift Solenoid 'B' is damaged or has failed
- The transmission is damaged or has failed

Reference Sources

[Acura P1751](#), DTCDECODE.