

ACURA P1780: PROBLEM IN SHIFT CONTROL SYSTEM (TRANSMISSION IS IN DEFAULT MODE)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Does The Acura P1780 Code Mean?

The A/T control switches to the default mode due to a mechanical malfunction. The execution time is continuous depending on the driving pattern.

NOTE: DTC P1780 means there is one or more A/T DTCs about the shift control system. Before you troubleshoot, record all freeze data and any on-board snapshot.

What Are The Potential Causes Of The Acura P1780 Code?

- Poor connections and loose terminals at the PCM
- PCM needs to be updated with the latest software
- Faulty PCM

Reference Sources

[Acura P1780](#), DTCDECODE.