

ACURA P1786: A/T FAS SIGNAL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura P1786 Code Mean?

This code indicates the condition that key on or engine running; and the PCM detected an unexpected voltage condition on the A/T FAS signal circuit to the TCM.

What Are The Potential Causes Of The Acura P1786 Code?

Below are some potential causes of this DTC:

- A/T FAS signal circuit to the TCM is open
- A/T FAS signal circuit to the TCM is shorted to ground
- A/T FAS signal circuit to the TCM is shorted to VREF
- TCM or PCM has failed

Reference Sources

[Acura P1786](#), DTCDECODE.