

ACURA P1795: A/T ACCELERATOR POSITION SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Acura P1795 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the APP sensor signal circuit to the TCM.

Note: The D4 lamp on the dash will flash 20 times if this code is set.

What Are The Potential Causes Of The Acura P1795 Code?

- APP signal circuit to the TCM is open
- APP signal circuit to the TCM is shorted to ground
- APP signal circuit to the TCM is shorted to VREF
- APP sensor connector is disconnected or damaged
- TCM or PCM has failed

Reference Sources

[Acura P1795](#), DTCDECODE.