

AUDI P1005: TORQUE DIFFERENCE CYLINDER 2 LIMITING VALUE EXCEEDED

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

What Does The Audi P1005 Code Mean?

Engine running ECM in closed loop ECT > 50° C Time since engine start > 30 Sec.

Reference Sources

[Audi P1005](#), DTCDECODE.