

AUDI P1009: AIR MASS METER 1/2 IMPLAUSIBLE SIGNAL FROM LOAD DETECTION

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$50-\$500 |
| Can I Still Drive? | : | Yes |

What Does The Audi P1009 Code Mean?

Time after engine start, 20 camshaft revs Lambda control, Closed loop Engine load, >14.25% Throttle position, No fuel load ECT, >59.25° C Or Substitute ECT

What Are The Potential Causes Of The Audi P1009 Code?

- Check fuse
- Check for signal, voltage and ground
- Check harness for open or short
- Check connector for damage.

Reference Sources

Audi, 2013, [2014 A8/A8L/S8 Quick Reference Specification Book](#), page 322.