

Audi P1009: Air mass meter 1/2 implausible signal from load detection

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$50-\$500

Can I Still Drive?

:

Yes

What Does The Audi P1009 Code Mean?

Time after engine start, 20 camshaft revs Lambda control, Closed loop Engine load, >14.25% Throttle position, No fuel load ECT, >59.25° C Or Substitute ECT

What Are The Potential Causes Of The Audi P1009 Code?

- Check fuse
- Check for signal, voltage and ground
- Check harness for open or short
- Check connector for damage.

Reference Sources

Audi, 2013, [2014 A8/A8L/S8 Quick Reference Specification Book](#), page 322.