

AUDI P1160: INTAKE AIR TEMPERATURE (IAT) SENSOR -G72- SHORT CIRCUIT TO GROUND (GND)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Does The Audi P1160 Code Mean?

Malfunction Criteria and Threshold Value: Intake air temperature sensor voltage-< 0.14 V.

Monitoring Time Length: 480 mSec.

What Are The Potential Causes Of The Audi P1160 Code?

Below are some potential causes of this DTC:

- Fuse
- Wiring for a short circuit to each other, Battery (+), and Ground (GND).
- Electrical harness connector for damage, corrosion, loose or broken terminals.
- Intake Air Temperature (IAT) Sensor
- Engine Control Module (ECM)

Reference Sources

[Audi P1160](#), DTCDECODE.