

AUDI P12A2: FUEL RAIL PRESSURE SENSOR INAPPROPRIATELY HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$287-\$320
Can I Still Drive?	:	Yes (Short-term only)

What Does The Audi P12A2 Code Mean?

This code is set in this condition:

Engine speed > 600 RPM

EVAP purge adaptation < 22.00

Lambda control closed loop fuel cut off not active

What Are The Potential Causes Of The Audi P12A2 Code?

- Check for signal, voltage and ground
- Check harness for open or short
- Check connector for damage.

How Can You Fix The Audi P12A2 Code?

Check possible solutions below:

- Check for signal, voltage and ground
- Check harness for open or short
- Check connector for damage

Reference Sources

- Audi, 2013, [A3 Quick Reference Specification Book](#), page 140 & 160.
- Audi, 2014, [A7 Quick Reference Specification Book](#), page 205 & 238.
- Audi, 2014, [A6/S6 Quick Reference Specification Book](#), page 253, 277 & 279.
- Audi, 2014, [Q5/SQ5 Quick Reference Specification Book](#), page 199, 228 & 182.
- Audi, 2014, [Q7 Quick Reference Specification Book](#), page 190.
- Audi, 2014, [TT Quick Reference Specification Book](#), page 137 & 159.
- Audi, 2014, [A5/S5 Quick Reference Specification Book](#), page 231, 260 & 290.
- Audi, 2014, [A4/S4 Quick Reference Specification Book](#), page 193 & 221.
- Audi, 2014, [R8/Spyder Quick Reference Specification Book](#), page 156 & 182.
- Audi, 2014, [A8/A8L/S8 Quick Reference Specification Book](#), page 234, 275 & 325.