

AUDI P1328: CYLINDER 4-KNOCK CONTROL LIMIT ATTAINED

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$500
Can I Still Drive?	:	No

What Does The Audi P1328 Code Mean?

This code is set in this condition:

Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, and the ECM detected the Knock Sensor signal was more than the calibrated value.

What Are The Potential Causes Of The Audi P1328 Code?

Below are some potential causes of this DTC:

- Knock sensor circuit is open
- Knock sensor circuit is shorted to ground, or shorted to power
- Knock sensor is damaged or it has failed
- ECM has failed

Reference Sources

[Audi A4 Avant 95-01 Service Repair Manual](#), page 46.