

AUDI P1360: CYLINDER 2 IGNITION CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$400
Can I Still Drive?	:	No

What Does The Audi P1360 Code Mean?

Key on or Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, and the ECM detected the voltage of the ignition was outside the designed parameters.

What Are The Potential Causes Of The Audi P1360 Code?

- Fuel pump relay faulty
- Camshaft position sensor has failed
- Engine speed sensor has failed
- Circuit wires have shorted to ground or are open
- Ignition coils with power output stages are faulty
- ECM has failed

Reference Sources

[Audi P1360](#), DTCDECODE.