AUDI P13D1: SENSOR FOR INTERNAL PRESSURE OF CYLINDER 2 ELECTRICAL MALFUNCTION OVERVIEW Severity : High DIY Difficulty Level : Intermediate Repair Cost : \$100-\$250 Can I Still Drive? : No

What Are The Potential Causes Of The Audi P13D1 Code?

- Faulty Glow Plug in Cylinder 2
- Glow Plug in Cylinder 2 harness is open or shorted
- Glow Plug in Cylinder 2 circuit poor electrical connection

Reference Sources

<u>Technical Service Bulletin for P13D1</u> - Audi of America, Inc; 2010–2014 A3 TDI & 2015 A3 Sportback TDI

