

AUDI P1424: SECONDARY AIR INJECTOR SYSTEM (BANK 1) LEAK DETECTED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes

What Does The Audi P1424 Code Mean?

Ignition on or vehicle running, and the ECM detected a leak in the secondary air injector system.

What Are The Potential Causes Of The Audi P1424 Code?

- Poor hose/pipe connections between the secondary air injector pump motor and valve
- Faulty hoses or pipes
- Mechanical faults in the secondary air injector system

Reference Sources

[Audi A4 Avant 95-01 Service Repair Manual](#), page 50.