

## AUDI P1498: SECONDARY AIR INJECTION SYSTEM INSUFFICIENT FLOW BANK 4

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$200-\$400                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Audi P1498 Code Mean?

Mass air flow, 24–140 kg/h ECT, 5.3.. .60° C IAT, > 5.3° C Altitude, <2600 m Delta engine load, <7%/rev Functional check, ready, no faults Mass air flow (), 14–60 kg/h Vehicle speed, <3.1 MPH Mass air intergral after start, >3 Kg Delta engine load, <10%/rev Engine speed, idle

### Reference Sources

- Audi, 2014, [A8/A8L/S8 Quick Reference Specification Book](#), page 327.
- Audi, 2014, [R8/Spyder Quick Reference Specification Book](#), page 157.