## AUDI P1500: FUEL PUMP RELAY CIRCUIT ELECTRICAL MALFUNCTION OVERVIEW Severity: Medium DIY Difficulty Level: Intermediate Repair Cost: \$100-\$200 Can I Still Drive?: Yes (Short-term only)

## What Does The Audi P1500 Code Mean?

This code indicates the condition that the engine is running and the ECM detected that the fuel pump relay signal was intermittent.

## What Are The Potential Causes Of The Audi P1500 Code?

Below are some potential causes of this DTC:

- Fuel delivery unit connector is loose or not attached
- Fuse 18 cause a short to the transfer fuel pump or the O2S
- Fuel pump has failed
- Fuel pump relay circuit is shorted to ground, B+ or is open
- Fuel pump (FP) Relay not activated
- ECM has failed

## **Reference Sources**

Audi A4 Avant 95-01 Service Repair Manual, page 54.

