		OVERVIEW	
		OVERVIEVV	
Severity	:	Medium	
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$100-\$200	

## What Does The Audi P1502 Code Mean?

Engine running the ECM detected that the fuel pump relay signal was intermittent

## What Are The Potential Causes Of The Audi P1502 Code?

- Fuel delivery unit connector is loose or not attached
- Fuse 18 cause a short to the transfer fuel pump or the O2S
- Fuel pump has failed
- Fuel pump relay circuit is shorted to ground, B+ or is open
- Fuel Pump (FP) Relay not activated
- ECM has failed

## **Reference Sources**

Audi A4 Avant 95-01 Service Repair Manual, page 54.

