

AUDI P1512: INTAKE MANIFOLD CHANGEOVER VALVE CIRCUIT SHORT TO B+

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$300-\$750
Can I Still Drive?	:	Yes

What Does The Audi P1512 Code Mean?

Engine started, and the ECM detected the changeover valve circuit was shorting to positive during the continuous self test.

What Are The Potential Causes Of The Audi P1512 Code?

- Leaky vacuum reservoir, vacuum lines loose or damaged
- Vacuum solenoid or vacuum actuator is damaged
- IMRC actuator cable/gears are seized, or the cables are improperly routed or seized
- IMRC housing return springs are damaged or disconnected

Reference Sources

[Audi P1512](#), DTCDECODE.