

## AUDI P1516: INTAKE MANIFOLD RUNNER CONTROL INPUT ERROR (BANK 1)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	<b>\$100-\$200</b>
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Audi P1516 Code Mean?

This code indicates the condition that key on or engine running; and the ECM detected the IMRC Monitor signal for Bank 1 was outside of its expected calibrated range during the continuous self test.

### What Are The Potential Causes Of The Audi P1516 Code?

Below are some potential causes of this DTC:

- IMRC mechanical fault – the linkage may be bound or seized
- Inspect for binding or improper routing. The cable core wire at the IMRC/IMSC housing attachment must have slack and lever must contact close plate stop screw

### Reference Sources

[Audi P1516](#), DTCDECODE.