

AUDI P1519: INTAKE MANIFOLD RUNNER CONTROL STUCK CLOSED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The Audi P1519 Code Mean?

Key on, and the ECM detected the IMRC Monitor was more than the expected calibrated range at closed throttle.

What Are The Potential Causes Of The Audi P1519 Code?

- IMRC monitor signal circuit shorted to power ground
- IMRC Monitor signal circuit shorted to signal ground (return)
- IMRC actuator is damaged or has failed (e. g. , there may be a small leak in the vacuum diagram of the actuator)
- ECM has failed

Reference Sources

Omnitek Engineering Corp., 2006, [Diagnostic Trouble Code \(DTC\) Guide for Omnitek ECM 64A/66A/88A](#), page 135.