

AUDI P1564: IDLE SPEED CONTROL THROTTLE POSITION LOW VOLTAGE DURING ADAPTATION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$850
Can I Still Drive?	:	No

What Does The Audi P1564 Code Mean?

Engine started, battery voltage at least 11.5v, all electrical components off, ground connections between engine and chassis well connected, coolant temperature at least 80-degrees Celcius and the throttle valve must not be damaged or dirty.

What Are The Potential Causes Of The Audi P1564 Code?

- Alternator failed
- ECM failed
- Fuses blown or open circuits
- Clean Throttle Valve Control Module
- Faulty battery
- Idle speed control throttle failed
- Wire connections to relay carrier and ground connection of ECM may have shorted

Reference Sources

[Audi A4 Avant 95-01 Service Repair Manual](#), page 57.