MALFUNCTION			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$400-\$850	

What Does The Audi P1580 Code Mean?

Comparison with throttle movement.

What Are The Potential Causes Of The Audi P1580 Code?

- The throttle position actuator Bank 1 circuit is open
- The ECM has failed
- The throttle valve control module circuit is open
- The throttle position actuator has failed

Reference Sources

Audi P1580, DTCDECODE.

