

AUDI P1681: CONTROL UNIT PROGRAMMING NOT FINISHED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	No

What Does The Audi P1681 Code Mean?

Reprogramming bit not set.

What Are The Potential Causes Of The Audi P1681 Code?

- Reprogram the Engine Control Module (ECM)
- ECM has failed

Reference Sources

[Audi P1681](#), DTCDECODE.