

## AUDI P17BA: CLUTCH POSITION SENSOR

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Audi P17BA Code Mean?

Malfunction Criteria and Threshold Value:

Short to Battery (+), sensor output Voltage high, > 4.5 V

### Reference Sources

Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 181.