

## AUDI P17BB: SHIFT POSITION SENSOR

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

### What Does The Audi P17BB Code Mean?

Engine start, completed Gear Shift. not in progress

### Reference Sources

Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 181.