AUDI P1850: DATA-BUS DRIVE TRAIN MISSING MESSAGE FROM ENGINE CONTROL MODULE

OVERVIEW

Severity : Medium

DIY Difficulty Level : Advanced

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Does The Audi P1850 Code Mean?

No signal within 300 ms, CAN bus ok –500 ms after ign. ON.

What Are The Potential Causes Of The Audi P1850 Code?

- Check the Terminal resistance for CAN-bus
- Data-Bus wires have short
- Data-Bus components are malfunctioning
- ECM has failed

Reference Sources

Audi P1850, DTCDECODE.

