

AUDI P1850: DATA-BUS DRIVE TRAIN MISSING MESSAGE FROM ENGINE CONTROL MODULE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Audi P1850 Code Mean?

No signal within 300 ms, CAN bus ok -500 ms after ign. ON.

What Are The Potential Causes Of The Audi P1850 Code?

- Check the Terminal resistance for CAN-bus
- Data-Bus wires have short
- Data-Bus components are malfunctioning
- ECM has failed

Reference Sources

[Audi P1850](#), DTCDECODE.