



AUDI P3028: ANGLE SENSOR 2 (ON THROTTLE DRIVE 2 POWER ACCELERATOR ACTUATION)

OVERVIEW

Severity	:	 Medium
DIY Difficulty Level	:	 Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes

What Does The Audi P3028 Code Mean?

TPS electrical range no failure unthrottled condition not fulfilled engine speed > 480 or engine speed > 1200 TPS electrical range no failure unthrottled condition not fulfilled engine speed > 480

Reference Sources

- Audi, 2013, [A8/A8L/S8 Quick Reference Specification Book](#), page 301.
- Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 142.