## AUDI P3035: THROTTLE VALVE CONTROL MODULE 2 MECHANICAL MALFUNCTION OVERVIEW Severity : High DIY Difficulty Level : Advanced Repair Cost : \$400-\$900 Can I Still Drive? : No

## What Does The Audi P3035 Code Mean?

fuel cutoff active throttle position setpoint limitation inactive Engine speed, < = 300 RPM IAT, >5° C Vehicle speed, < = 0 MPH ECT, > = 5.3° C IAT > = 5.3° C

## **Reference Sources**

- Audi, 2013, A8/A8L/S8 Quick Reference Specification Book, page 301.
- Audi, 2013, R8/Spyder Quick Reference Specification Book, page 142.

