

AUDI P3035: THROTTLE VALVE CONTROL MODULE 2 MECHANICAL MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$900
Can I Still Drive?	:	No

What Does The Audi P3035 Code Mean?

fuel cutoff active throttle position setpoint limitation inactive Engine speed, < = 300 RPM IAT, >5° C
Vehicle speed, < = 0 MPH ECT, > = 5.3° C IAT > = 5.3° C

Reference Sources

- Audi, 2013, [A8/A8L/S8 Quick Reference Specification Book](#), page 301.
- Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 142.