

## AUDI P3081: ENGINE TEMPERATURE TOO LOW

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

### What Does The Audi P3081 Code Mean?

Maximum reference temperature, 60 °C

### What Are The Potential Causes Of The Audi P3081 Code?

- Let engine warm up.
- Engine Coolant Temperature (ECT) Sensor.
- Check the wiring for an open circuit, a short circuit to each other, Battery (+), or Ground (GND).
- Replace ECM

### Reference Sources

- Audi, 2013, [A8/A8L/S8 Quick Reference Specification Book](#), page 301.
- Audi, 2013, [R8/Spyder Quick Reference Specification Book](#), page 142.